




OCTO INSPECTORS LLC

4049027936

octoinspectors.bc@gmail.com



BRAN CARTER

3711 Tulip Dr
Decatur GA 30032

Justin Carter
AUGUST 24, 2021



Inspector

Brandford Carter

ICA certified & interNACHI member

4045207017

octoinspectors.bc@gmail.com

SUMMARY

7

RECOMMENDATION

2

SAFETY HAZARD

- ⊖ 2.1.1 Roof - Coverings: Improper/Incomplete Nailing
- ⊖ 3.3.1 Exterior - Walkways, Patios & Driveways: Driveway Cracking - Minor
- ⚠ 7.2.1 Plumbing - Drain, Waste, & Vent Systems: Improper Connection
- ⊖ 7.4.1 Plumbing - Hot Water Systems, Controls, Flues & Vents: Corrosion
- ⊖ 7.4.2 Plumbing - Hot Water Systems, Controls, Flues & Vents: Near End of Life
- ⊖ 11.2.1 Doors, Windows & Interior - Windows: Damaged
- ⊖ 11.5.1 Doors, Windows & Interior - Ceilings: Minor Damage
- ⚠ 11.5.2 Doors, Windows & Interior - Ceilings: Sagging Drywall
- ⊖ 12.3.1 Built-in Appliances - Range/Oven/Cooktop: Burner Not Lighting